

## Tooling E2

Compression	Tip	GDA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
	3		Alloy for fluoropolymer		
	4		Tungsten carbide		
	9		Steel with diamond insert		
	Die	FDA0010...	1	Hardened steel	
			4	Tungsten carbide	
Semi-compression	Tip	GDA0020...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
	4		Tungsten carbide		
	9		Steel with diamond insert		
	Die	FDA0020...	1	Hardened steel	
			4	Tungsten carbide	
Tube	Tip	GDA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
	3		Alloy for fluoropolymer		
	4		Tungsten carbide		
	Die	FDA0030...	1	Hardened steel	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	

Examples:

Compression die, tungsten carbide  
Semi-compression tip, tungsten carbide  
Tube tip, hardened steel

FDA00104  
GDA00204  
GDA00301

D6=...  
D1=...  
D1=... D2=...

## Tooling E3

Tube	Tip	GDA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	

## Tooling E4

Compression	Tip	GAA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
Semi-compression	Tip	GAA0020...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0020...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
Tube	Tip	GAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Tip	GAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
Die	FAT0030...	1	Hardened steel		
		2	Steel with tungsten carbide insert		
		3	Alloy for fluoropolymer		
		4	Tungsten carbide		

Examples:

Compression die, steel with tungsten carbide insert  
Semi-compression tip, tungsten carbide  
Tube tip, hardened steel

FAA00102  
GAA00204  
GAA00301

D6=...  
D1=...  
D1=... D2=...

## Tooling E12/E14

Compression	Tip	GBA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			9	Steel with diamond insert	
	Die	FBA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
3			Alloy for fluoropolymer		
Semi-compression	Tip	GBA0022...	1	Hardened steel	
			2	steel with tungsten carbide insert	
			9	Steel with diamond insert	
	Die	FBA0022...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
Tube	Tip	GBA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
	Die	FBA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	

Examples:

Compression die, Alloy for fluoropolymer  
Semi-compression tip, steel with tungsten carbide inserts  
Tube tip, hardened steel

FBA00103

GBA00222

GBA00301

D6=...

D1=...

D1=... D2=...

## Tooling E25

Compression	Tip	GTA0010...	1	Hardened steel	
	Die	FTA0010...	1	Hardened steel	
Semi-compression	Tip	GTA0022...	1	Hardened steel	
	Die	FTA0022...	1	Hardened steel	
Tube	Tip	GTA0030...	1	Hardened steel	
			3	Alloy for fluoropolymer	
Die			1	Hardened steel	
			3	Alloy for fluoropolymer	

Examples:

Compression die, hardened steel

FTA00101

D6=...

Semi-compression tip, hardened steel

GTA00221




D1=...

Tube tip, Alloy for fluoropolymer

GTA00303

D1=... D2=...

### Tooling for CARTRIDGES E4K 4.1.0

Compression	Tip	GAA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
Semi-compression	Tip	GAA0020...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0020...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
Tube	Tip	GAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	
	Die	FAA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			4	Tungsten carbide	

Examples:

Compression die, steel with tungsten carbide insert

FAA00102

D6=...

Semi-compression tip, tungsten carbide

GAA00204

D1=...

Tube tip, hardened steel

GAA00301

D1=... D2=...

## Tooling for CARTRIDGES E4K 4.3.0

Compression	Tip	GAF0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			9	Steel with diamond insert	
	Die	FAA0010...	1	Hardened steel	
			3	Alloy for fluoropolymer	
Semi-compression	Tip	GAF0021...	1	Hardened steel	
			2	steel with tungsten carbide insert	
			9	Steel with diamond insert	
	Die	FAA0021...	1	Hardened steel	
			2	Steel with tungsten carbide insert	

## Tooling for CARTRIDGES E12K 12.2.0

Compression	Tip	GBA0010...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	
			9	Steel with diamond insert	
	Die	FBA0010...	1	Hardened steel	
			3	Alloy for fluoropolymer	
Semi-compression	Tip	GBA0022...	1	Hardened steel	
			2	steel with tungsten carbide insert	
			9	Steel with diamond insert	
	Die	FBA0022...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
	Tube	Tip	GBA0030...	1	
2				Steel with tungsten carbide insert	
3				Alloy for fluoropolymer	
Die		FBA0030...	1	Hardened steel	
			2	Steel with tungsten carbide insert	
			3	Alloy for fluoropolymer	